

Silva House
(Kingsway Center Commercial Area)
1333 Euclid Avenue
St. Louis
St. Louis County
Missouri

HABS No. MO-60-K

HABS
MO,
96-SALU,
133-K-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA


Historic American Buildings Survey
National Park Service
Rocky Mountain Regional Office
Department of the Interior
P.O. Box 25287
Denver, Colorado 80225

NATIONAL PARK SERVICE

ROCKY MOUNTAIN REGION


ARCHITECTURAL DATA FORM

STATE MISSOURI	COUNTY	TOWN OR VICINITY CITY OF SAINT LOUIS
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Silva House (Permits)		EABS NO. MO-60-K
SECONDARY OR COMMON NAMES OF STRUCTURE		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 1333 Euclid Avenue		
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1891 (Permits)	ARCHITECT(S) (INCLUDE SOURCE) Louis J. Silva (Permits) Owner	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The Kingsway Center Area is locally significant for its architectural significance as an important representative illustration of neighborhood development and urban vernacular building traditions in late 19th-century St. Louis. The Silva House is one of the bldgs. in the area that contributes to a potential historic district. Original Use: single-family residence.		
STYLE (IF APPROPRIATE) Queen Anne		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Hubble stone foundation. Partial basement with concrete floor. Brick, asphalt shingle wall. Masonry & wood frame. Galvanized gutters & downspouts. Hipped-slate roof. Hardwood & vinyl floors. Plaster wall & ceilings. Cast iron & galvanized plumbing. Gas forced warm air heating. Incandescent lighting.		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Site Plan Attached.		
EXTERIOR FEATURES OF NOTE The building consists of a central dormer with an onion dome & finial & an overhang supported by a curved bracket with a drop springing from the pilaster dividing lights below. It has a cornice of raised brick dentil & a diamond-point moulding course above segmental arches; it has a bull's eye course at the lintel level. There is a wood arch with plain infill. At the masonry sill lines, there is a decorative course in a herringbone pattern. A gabled porch across the lower facade has been altered.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Site Plan Attached.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Records of the building permit division of the City of St. Louis show that a one-story brick garage was constructed in December, 1927; that a new section was added onto the dwelling in June, 1933; and that perma stone was applied to the lower facade and porch in August, 1970.		
PRESENT CONDITION AND USE Good condition. Single-family residence.		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Building Division of the City of St. Louis. Records of the City Assessor. Appraisal report-Real Estate Analysts, Ltd. Report of Cultural Resource Assessment-Archaeological Survey, University of Missouri-St. Louis. Gould's City Directory/Blue Book, 1893, 1896, 1897, and 1898. Notification from the Keeper of the National Register and the Missouri Historic Preservation Program.		
COMPILER, AFFILIATION Claude L. Luchessa, Project Manager		DATE 11 10 1996




SILVA HOUSE
1333 Euclid Ave
St. Louis, MO
August 1, 1986

1ST FLOOR



SILVA HOUSE
1333 Euclid Ave
St. Louis, MO
August 1, 1986

2ND FLOOR



SILVA HOUSE
1333 Euclid Ave
St. Louis, MO
August 1, 1986

ATTIC